

## Bombardier Global 7500 / SN 70018



### **Highlights**

2020 In Service US Registered and Based Aft Suite with Bed and Shower KA Band High Speed Data 40" HD Monitor Crew Rest Third Crew Jump seat Crew Force Measurement System Engine Program APU Program

For more information: Mark Bloomer or Brant Dahlfors Corporate Office: 220 Newport Center Drive • Suite 11-600 • Newport Beach, CA 92660 • Phone (805) 484-6605 • info@jettransactions.com SPECIFICATIONS SUBJECT TO VERIFICATION UPON INSPECTION

### AIRFRAME

In-Service Date: Total Time (HRS): Landings: Registration

### ENGINES:

Model: Enrolled on :

Serial Number: Hours Since New: Cycles Since New: Intervals:

#### APU

Model: Serial Number: Time Since New (HRS): Enrolled on: June 2020 724.8 342 N762F (Seller to retain N#)

GE Passport 20-19BB1A GE OnPoint Engine Program Engine 1 Engine 2 904137 904138 724.8 724.8 349 349 On Condition On Condition

SPU300 [BA] SPUA-E1838035 980 Safran PowerCare





AVIONICS	Quantity	Description
Avionics Package		Collins Pro Line Fusion
Audio Panel (Digital)	3	Collins ACP-6000
Automatic Direction Finder (ADF)	2	Collins NAV-4000
Cockpit Voice Recorder (CVR)	1	L3 FA5000
Communication Transceivers (VHF)	3	Collins VHF-4000
Distance Measuring Equipment (DME)	2	Collins DME-4000
Emergency Locator Transmitter (ELT)	1	Artex 406
Enhanced Vision System	1	Bombardier
Flight Data Recorder (FDR)	1	L3 FA5000
Flight Management System (FMS)	3	Integrated
Global Positioning System (GPS)	2	Collins GPS-40005
Ground Proximity (EGPWS)	1	Collins TPM-6000
Head Up Guidance System (HGS)	1	Bombardier
HF Radio (HF)	2	Collins HF-9031A
Inertial Reference System (IRS)	3	Honeywell IR-600 (LASEREF VI)
Navigation	2	Collins NAV-4000
Radio Altimeter	2	Collins ALT-4000
Synthetic Vision System (SVS)	1	Collins SVM-6110H
Traffic Collision Avoidance System (TCAS	) 1	Collins TCAS II w/ Change 7.1
Transponder	2	Collins TDR-94D + TSS-4100 w/ ADS-B
Weather Radar	1	Collins RTA-4218

# **ADDITIONAL FEATURES**

Lightning Detection System Activation of Vertical Weather Radar (SB 700-34-7502) Predictive Windshear (SB 700-34-7501)

<image>

#### **INTERIOR CONFIGURATION:**


Forward Galley

Crew Rest & Crew Lav

3<sup>rd</sup> Crew Seat

Cabin Seating for 13:

- ZONE 1:Dual 2 Place ClubsZONE 2:4-Place Conference Group Opposite CredenzaZONE 3:2 Place Club opposite a 3-Place DivanZONE 4:Bed Opposite Credenza
  - Aft Lav with Shower (30 Gallon Tank)



#### **CABIN ENTERTAINMENT AND EQUIPMENT** Jetwave KA Band HSD Lufthansa Nice Touch Cabin Management System (CMS) 24-inch LCD Monitor - Zone 1 40-inch Stand Up LCD Monitor on Zone 2 Credenza 32-inch LCD Monitor - Aft Stateroom

# GALLEY EQUIPMENT

Convection / Steam Oven

Provision Space for Coffee Maker

Microwave Oven











SPECIFICATIONS SUBJECT TO VERIFICATION UPON INSPECTION.







**EXTERIOR** Champaign gold top with dark brown belly and accents.

# MAINTENANCE INSPECTIONS

24 Month Insp.36 Month (850 Hour) Insp.72 Month Insp.120 Month Insp.

Due March 2024 C/W March 2023 Due April 2026 Due April 2030

## MAINTENANCE PROGRAMS

Engines: APU: Maintenance Tracking: GE On-Point Safran PowerCare Flightdocs



For more information, please contact: Mark Bloomer or Brant Dahlfors Phone: (805) 484-6605 E-Mail: info@jettransactions.com www.jettransactions.com