

2002 Gulfstream GV s/n 665

HIGHLIGHTS

Engines Enrolled on RRCC • GoGo Avance L5 System

NextGen Ready

AIRFRAME: as of 01.26.2021

Total Time: 6229 Cycles: 2284

APU: HONEYWELL RE220-GV JSSI Enrollment Nov. 1, 2015

S/N: P279 TSN: 3985 **ENGINES:** ROLLS-ROYCE – BR700-710C4-10 Enrolled on Rolls Royce Corporate Care

Left Engine: Right Engine: S/N: 11445 S/N: 11446 TSN: 6229 TSN: 6229 Cycles: 2284 Cycles: 2284

Engines are On Condition.

AVIONICS

Honeywell SPZ-8500 Avionics
Six (6) Honeywell DU-880 Display Units
Triple Collins VHF-422C VHF Comms
w/ 8.33 Spacing
Dual Collins VIR-432 VHF Navs
Dual Collins ADF-462ADF's
Dual Collins DME-442 DME's
Single Collins DME-622-6524-001 DME
Dual Collins TDR.-94D Mode S Transponders
(ELS Flight ID Compliant 622-9210-409)
Honeywell WU-880 Weather Radar
Triple Honeywell IC800E Version 6.0 FMS
Triple Honeywell CDU-820 FMS CDU's
Honeywell DL-950 Data Loader
Triple Honeywell Laseref IV IRS

Honeywell EGPWS Mark V w/RAAS
Dual Collins HF-9034A HF Systems
Dual Honeywell RT-300 Radio Altimeters
Heads Up Display (HUD)
Kollsman Enhanced Vision System (EVS)
w/Co-Pilots Repeater Monitor
Honeywell TCAS 2000 with change 7.1
Honeywell AFIS DMU
Dual Honeywell FC-880 Fault Warning Computer
GH-3000 Standby Attitude Indicator
Dual Honeywell DA-800 Data Acquisition Units
L3 Communications S151 CVR
L3 Communications FA2100 FDR
L3 mQAR for FOQA Analysis
AirCell ST-3120

NEXTGEN:

FANS 1/A

ASC 214 ADS-B Out Version 2

ASC 186B FMS 6.1 Software SBAS/LPV GPS Installation

SWIFTBROADBAND HD-710 (for use with Universal system to comply with CPDLC)

INTERIOR: Soft Goods Refurb Sep. 2015

Fourteen (14) passenger interior (Plus Crew Rest and Jumpseat) featuring a forward four (4) place club arrangement followed by a mid-cabin four (4) place divan opposite a two (2) place club. The aft cabin offers a four (4) place conference group opposite a credenza.

Aft full service galley includes a high temp oven, microwave and dual TIA coffee makers. Forward crew lavatory and full size aft lavatory. Flight Phone locations include crew rest area, VIP seat, mid cabin left chair, conference table and the galley.



Entertainment System:

Honeywell HD-710 with a Satcom Direct Router with 3G/4G antenna

GoGo Avance L5 System

AM/FM Stereo w/10 Disc CD Changer

Four (4) Individual 5.6" Monitors

DVD & VCR Player Three (3) External Cameras

Forward 17' LCD Bulkhead Monitor and 14" monitor above the credenza.

Materials:

Single seats are done in Italian cowhide Andes Altiplanos colored leather. (New Sept. 2015)

The divan is completed in Italian velvet vapor colored fabric. (New Sept. 2015)

Medium honey toned cabinetry is complimented by the Gold plating.

Ivory Ultra leather headliner.

New window panels (Oct. 2014)

Oyster colored carpeting. (New Sept. 2015)

EXTERIOR: Overall Matterhorn White w/ Deep Royal Blue & Super Jet Black Accent Striping. (Sept 2018)

MAINTENEACE AND PROGRAMS:

Engines Enrolled on RRCC APU enrolled on JSSI

Pneumatic System w/Honeywell protection plan

Avionics on HAPP Honeywell protection plan 192 Month Complied with Sept 2018



























